

ENGLISH



WARNINGS

POLYKEG PRO 2.0



PolyKeg PRO 2.0 is a vessel designed for the transport and distribution of drinks.

Before using the PolyKeg keg, **please read the user manual** carefully and follow the instructions. Improper use of the PolyKegs can damage it and cause dangerous situations.

Always check the integrity of the keg before use and **do not compromise the legibility of the label** on the keg in any way.

If damage such as dents, cuts or other damage is found, do not use the keg and contact your dealer.

Before handling the keg, **wear personal protective equipment** (goggles, gloves, etc.) and ensure that the room where you are working is ventilated.

The PolyKeg keg may not be reused, may not be disposed of in the environment and must be depressurised immediately after use and returned empty to a collection point or other authorised recycling system.

SAFETY SYMBOLS



Keep away from children. When the keg is under pressure it is heavy and can cause injury and/or property damage.



Keep away from chemicals or unsuitable cleaning substances. The keg may be damaged, not ensuring the integrity of the product or causing injury and/or property damage.



Do not remove and/or tamper with the valve. The keg may be damaged, not ensuring the integrity of the product or causing injury and/or property damage.



Whenever using or handling, keep the keg away from vital parts of the body



Do not expose to direct sunlight. The keg may be damaged, not ensuring the integrity of the product or causing injury and/or property damage.



Do not pierce and/or cut. The keg may be damaged causing injury and/or property damage.



Do not roll and/or drop. The keg may be damaged causing injury and/or property damage.



Keep the keg away from open flames or other heat sources.

OBLIGATION SYMBOLS



Carefully consult the user manual and follow the instructions. Improper use can damage the keg and cause dangerous situations.



Depressurise the keg immediately after use as indicated in the appropriate section of the manual. This operation must be followed before the keg is disposed of at collection points.



Always use personal safety equipment whenever using the keg (e.g. handling, connecting and disconnecting, depressurising, etc.).



Always use personal safety equipment whenever using the keg (e.g. handling, connecting and disconnecting, depressurising, etc.).

WARNING SYMBOLS



0÷40 °C
32÷104 °F

Keep away from heat sources. If exposed to temperatures above the permitted limit the keg may be damaged, not ensuring the integrity of the product or causing dangerous situations.



MAX 3,5 BAR
50 PSI

If over-pressurized, the keg may cause dangerous situations.



DANGER
N₂ - CO₂ GAS
INSIDE

Suffocation hazard. Use the keg in a well-ventilated environment.



Damage to the keg can cause dangerous situations